

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

September 30, 2016

Certified Return Receipt Requested 7013 2250 0000 2310 2804

Brent Sumsion Sunroc Corporation P. O. Box 1955 Orem, Utah 84059

Subject: Modified Division Directive to Repair Road Damage and Remove Undercut Highwall, Sunroc

Corporation, Levan Henry Mine, M/023/0023, Juab, County, Utah

Dear Mr. Sumsion:

By letter dated September 22, 2016, the Division of Oil, Gas and Mining directed you to complete certain road drainage maintenance work, but you stated in a telephone conversation with Wayne Western that constructing or repairing the ditch on the uphill side of the road would cause erosion problems.

It appears, therefore, that the drainage control plan in the Notice of Intention to Commence Large Mining Operations (Notice) needs to be modified to better address drainage from the road.

By October 31, 2016, please submit an amendment to the Notice showing how drainage from the road will be properly controlled. Please also evaluate whether the drainage control plans for other areas are sufficient.

Please contact Wayne Western at 801-538-5263 or me at 801-538-5261 if you have questions or concerns regarding this letter. Thank you for your help in completing these regulatory requirements.

Sincerely,

Paul B. Baker

Minerals Program Manager

PBB: whw: eb

cc: Tom Lloyd, Forest Service (twlloyd@fs.fed.us); Steven Polgar, MSHA (Polgar.Steven@dol.gov) P:\GROUPS\MINERALS\WP\M023-Juab\M0230023-Henry1and2\final\Directive-7474-09292016.docx

